

---

Reference:

NTB13-014

Date:

March 7, 2013

VOLUNTARY SERVICE CAMPAIGN 2009 – 2011 STEERING LOCK UNIT

CAMPAIGN ID #:

APPLIED VEHICLES: 2009 – 2010 370Z (Z34)

INTRODUCTION

P3208

2009 – 2011 GTR (R35)

Check Service COMM to confirm campaign eligibility.

Nissan is conducting a Voluntary Service Campaign to replace the steering lock assembly on certain specific 2009 – 2010 model year 370Z and 2009 – 2011 model year GTR vehicles due to excessive oil within the assembly, which could cause the Body Control Module (BCM) to prevent the engine from starting when the ignition is cycled. This issue does not affect steering or engine operation when the vehicle is already running.

IDENTIFICATION NUMBER

Nissan has assigned identification number P3208 to this campaign. This number must appear on all communications and documentation of any nature dealing with this campaign.

DEALER RESPONSIBILITY

Dealers are to repair vehicles falling within range of this campaign that enter the service department. This includes vehicles purchased from private parties, vehicles presented by transient (tourists) owners, and vehicles in a dealer's inventory

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'.

Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.